

Optimate 12V
DC → DC 12V 2A

12V 2A
6 STEPS

Charge your 12V battery from another 12V battery!

TM-500

Charge without AC power

Maintain remote battery

SAVE your 'dead' battery



WEATHERPROOF CASE
with WALL MOUNTS
❄️ 'ARCTIC' CABLE

1

Low Volt Start (1V)

2

Pulse SAVE

3

Controlled CHARGE

4

OPTIMIZE

5

TEST after CHARGE

6

OptiMate maintenance



CHARGING AMPS	2A
USE	INDOOR / OUTDOOR ❄️ t°min: -40°C
SAVE	Low Volt start 2V + 2 Step desulfation recovery
IDEAL FOR	 6 - 96Ah
CABLE ACCESSORIES	